

DAILY INCIDENT REPORT RECEIVED FROM DDMA_s as on 29.08.2024 till 9:00 Pm

Sl. No.	Name of District	Type of Incident	Affected Areas (Towns/Villages)	Affected Population	Date of Incident	Preliminary Assessment of Damage/Loss of Lives, Properties, Houses, etc.	Remarks
1	Aizawl	Landslide	Muanna Veng, Zuangtui		29.08.2024	Route to Govt Primary School road block due to Landslide.	The road is not under the maintenance of PWD
2	Lunglei						
3	Siaha						
4	Champhai						
5	Kolasib	Landslide	Thingdawl	1 family	27.08.2024	1 house belonging to Pu Tlangsawiluaia fully damaged	The local community re-construct house using the old structure and they are currently staying in that house.
6	Serchhip	Landslide	NH 54 below Baktawng		29.08.2024	NH 54 below Baktawng was completely blocked due to landslide	Zonal Officer currently stuck due to road block
7	Lawngtlai						
8	Mamit	Landslide	Mamit- Bawngva Road		28.08.2024	Mamit - Bawngva road NH 44 A near Tuidal was blocked due to landslide	Road clearance and repair progress will be slow, PWD is working on the old road that will bypass it.
		Landcrack	Mamit, Bazar veng		29.08.2024	Pu Lalrinchhana Hrahse and Pu H. Lalchhuanawma house were damaged by landcrack	the two families have been evacuated.
			Mamit, Field veng		29.08.2024	Pi Lalliankimi's house effected by landcrack	The family have been evacuated.
9	Saitual						
10	Khawzawl						
11	Hnahthial	Land subsidence	Hnahthial		29.08.2024	Sinking of road occurred near Sericulture Office at Peniel Veng, Hnahthial.	Reconstruction and widening of road to be taken up in collaboration with ABCI Company

11	Hnahthial	Landslide	Hnahthial			Landslide occurred along Herhse Road at Chanmari Veng, Hnahthial, blocking internal road	Debris clearance taken up through VDMC, Hnahthial South-III
			Denlung			Landslide occurred along Hnahthial to Denlung approach road, blocking the road	Debris clearance taken up through VDMC, Denlung
			New Ngharchhip		29.08.2024	Landslide occurred along Cherhlun to Ngharchhip approach road via New Ngharchhip, blocking the road	Debris clearance taken up through VDMC, Ngharchhip and New Ngharchhip
			Muallianpui			Landslide occurred along South Vanlaiphai to Muallianpui approach road, blocking the road	Debris clearance taken up through VDMC, Muallianpui
			Lungmawi			Landslide occurred along Pangzawl to Lungmawi approach road, blocking the road	Debris clearance taken up through VDMC, Lungmawi